



Citation Excel N104LV S/N 5190

Specifications and Summary



2001 Citation Excel

N104LV S/N 5190



OFFERED AT: MAKE OFFER

AIRCRAFT HIGHLIGHTS:

WAAS/LPV
2ND FMS
Same Corporate Owner / Operator since 2006
(Part of a large private Citation Fleet)
No Damage History
2015 Interior
2016 Paint
Boom Beam STC
Max Vis EVS-1000

STATUS: As of September 30th, 2022

TOTAL TIME: 7,191

LANDINGS: 9,285

ENGINES: Pratt & Whitney PW545A

	LEFT	RIGHT
TOTAL TIME SINCE NEW:	6,890	6,814
TIME SINCE OVERHAUL:	1,960	459
OVERHAUL INTERVAL:	5,000	5,000

APU: Honeywell RE100(XL)

TSN: 4,550

CAPABILITIES:

WAAS/LPV
ADS-B Out Version 2

Boom Beam STC

AVIONICS & COCKPIT



AVIONICS: Honeywell Primus 1000

AIR DATA COMPUTER: Dual Honeywell AZ-850 ADC's
ATTITUDE HEADING REFERENCE SYSTEM: Dual AHRS Computers. LH LCR-93 and RH LCR-100
AUTOMATIC DIRECTION FINDER: Dual Honeywell DF-850 ADF
COCKPIT VOICE RECORDER : L3 Harris A200S 120 Minute SSCVR
COMMUNICATIONS : Dual Honeywell RCZ-833
DISTANCE MEASURING EQUIPMENT: Dual Honeywell DM-850 DME
EMERGENCY LOCATOR TRANSMITTER: Artex ELT C406-N w/ Integrated Nav Interface
ENHANCED VISION SYSTEM: Max Vis EVS-1000
ELECTRONIC FLIGHT INSTRUMENT DISPLAY: Triple Honeywell DU-870 Displays
FLIGHT MANAGEMENT SYSTEM: Dual UNS- 1Espw with LPV
NAVIGATION : Dual Honeywell RNZ-850 with DME
RADIO ALTIMETER: Collins ALT-55B
RADIO MANAGEMENT UNITS: Dual Honeywell RM-855 RMU's
STAND-BY FLIGHT DISPLAY: Meggitt Secondary Flight Display
TRAFFIC COLLISION AVOIDANCE SYSTEM: Bendix King TCAS II TPU-67A
TRANSPONDER: Dual Honeywell XS-852 Comm Unit
WEATHER RADAR: Honeywell Primus WU-880 Radar

MAINTENANCE PROGRAMS & INSPECTIONS STATUS



MAINTENANCE & INSPECTIONS

- Cescom 10/20 Available upon request
- MSG - 3
- Certificate of Airworthiness: 8/17/2001
- Document 6 (48 Month) & 16 (96 Month) Inspections Due August 2023
- Doc 11 (24 Month) & Doc 12 (60 Month) Inspections Due May 2023

INTERIOR Forward Cabin

INTERIOR DESCRIPTION (Interior Refurbished May 2015)

Nine passenger configuration with forward two-place couch opposite the main cabin door. The mid cabin features a four-place club followed by two forward facing club seats. An internally serviced belted aft lavatory completes this interior.

Galley Equipment: Hot Coffee Dispenser, Two-sided Ice Cooler.



Forward Cabin looking Aft

INTERIOR



Forward Cabin looking Forward

FORWARD GALLEY



Forward Crew Rest

AFT LAVATORY



Aft Lavatory

EXTERIOR

EXTERIOR DESCRIPTION

(Repainted August 2016)

Snow White with Black and Red Stripes



This aircraft is being brokered by Guardian Jet, LLC. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Guardian Jet, LLC makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications subject to verification upon inspection. Aircraft subject to prior sale.

2022 11 15 / JD